

•••••	<5 g/L
•••••	100%
•••••	7A:1B
•••••	1/4" x 1/4": 300 lf/gal
•••••	40°- 90°F
•••••	10 Min
	1 Hour
•••••	7 Days
	2 Gal Kit 10 Gal Kit
	······

# **MECHANICAL PROPERTIES**

TENSILE STRENGTH ASTM D638		2,200 p.s.i
ELONGATION ASTM D638	•••••	650%
TEAR STRENGTH ASTM D624		475 p.s.i

# CHEMICAL RESISTANCE

Refer to CrownTech Chemical Resistance Guideline Technical Bulletin No. 9

#### Technical Data Sheet (TDS)

# **PRODUCT DESCRIPTION**

7126 CrownFlex HA is a two-component, rapid setting, self-leveling, 100% solids, aliphatic polyurea joint sealant, and crack filler. It features a combination of excellent adhesion and elongation. 7126 CrownFlex HA is designed for exterior and interior control joints and crack caulk. It is used on control joints and cracks subjected to heavy foot traffic, forklift traffic, and chemical attack, specifically food acids. It is VOC Compliant in all states and provinces in North America.

## **TYPICAL USES**

Aircraft Hangars & Maintenance Floors
Automotive Show Room and Repair Areas

 Commercial Bakeries and Kitchens
 Hospital and Health Care Facility Floors Laboratories and Research Floors
Manufacturing and Warehouse Floors

School & Universities
Pharmaceutical Eloors

Floors

# BENEFITS

- Complies with USDA, FDA, FSMA. See Crown Polymers Technical Bulletin: 3 Food and Beverage Compliance.
- Slip Resistance (ADA)
  See Crown Polymers
  Technical Bulletin: 4
  Coefficient of Friction.

• LEED requirements. See Crown Polymers Technical Bulletin: 5 LEED information Cures to an inert
finish. See Crown Polymers
Technical Bulletin: 2 VOC
Compliance

## COLORS

Concrete Grey

## LIMITATIONS

• Higher temp/humidity will result in shortened working times and faster drying time.

• Color may vary due to batch-to-batch variation, always "box" different batches to avoid it.

## SHELF LIFE

1 Year from Date of Manufacture provided unopened

• Use 8303 CrownShield™ Moisture Barrier when MVT exceeds 3 lbs. or 80% RH

• Do not dilute with solvents

• Heavier applications take longer to cure

## STORAGE

Store in a dry environment at room temperature and out of direct sunlight.

## DISCLAIMER

All technical bulletins, installation guidelines, guidelines, recommendations, statements, specifications, and technical data contained herein are based on information and tests. The accuracy and completeness of such tests are not guaranteed and are not to be construed as a warranty, expressed or implied. It is the responsibility of the user to document information and tests to determine the intent of the product for ones' own use. The application, job conditions and user assume all risks and liability resulting from use of the product, We do not suggest or guarantee any hazards listed herein are the only ones, which may exist, Neither seller nor manufacturer shall be liable to the buyer or any third person for any injury, loss or damage directly or indirectly resulting from use of, or inability to use the product. Recommendations or statements, whether in written or verbal, other than those contained herein shall not be binding upon the manufacturer, unless in writing and signed by corporate officer of the manufacturer. Technical and application information is provided for the purpose of establishing a general profile of the material and proper application procedures. Test performance results were obtained in a controlled environment and Crown Polymers makes no claim that these tests or any other tests accurately represent all environments. Not responsible for typograhical errors.

#### LIMITED WARRANTY

Crown Polymers warrants its products to be free of manufacturing defects and meets all Crown Polymers current published physical properties. Crown Polymers' sole responsibility shall be to replace the protion of any product proved to be defective. There are no other warranties by Crown Polymers of any nature whatsoever expressed or implied, including any warranty of merchantability or fitness for a particular purpose in connection with this product. Crown Polymers shall not be liable for damages of any sort, including remote or consequential damages resulting from any claimed breach of any warranty expressed or implied. In addition, no warranty or guarantee pertaining to appearance, color, fading, chalking, staining, shrinkage, peeling, normal wear and tear or improper application by applicator will be issued. Damage caused by abuse, neglect and lack of proper maintenance, acts of nature and/or physical movement of substrate or structural defects are also excluded from limited warranty.



#### **APPLICATION EQUIPMENT**

Personal Protective Equipment Jiffy Mixing Paddle Drill Flat Squeegee Putty Knife

## SURFACE DIAGNOSTICS

Concrete must be structurally sound and free of all contaminants and bond breakers. Test concrete compressive strength using a Schmidt or Rebound Hammer to ensure substrate has compressive strength of 3500 psi or higher.

Perform a PH test using concrete PH test strips or meter to ensure substrate PH is between 9-12.

Perform Moisture Test using either Calcium Chloride per ASTM F1869 or In-Situ Relative Humidity Probe per ASTM F2170 to ensure substrate has Moisture Vapor Emission Rate of 3 lbs or less and Relative Humidity of 80% or less. See CrownTech Bulletin 6: Moisture Mitigation Negative Side Moisture Barrier

If Moisture Vapor Emission Rate is above 3 lbs. but below 25 lbs. and relative humidity is above 80% but below 99% then apply 8303 Moisture Barrier Primer first at 16 mils with a coverage rate of 100 Ft<sup>2</sup>/ Gal.

#### SURFACE PREPARATION

Use Mohs scratch test to determine concrete hardness for proper diamond bond selection.

Concrete should be mechanically profiled and prepared to produce a Concrete Surface Profile (CSP) level between #2 & #4 per ICRI Guideline no. 310.2R. See CrownTech Bulletin 1: Concrete Surface Preparation. All perimeter areas of coating termination shall be masked for protection. Saw cut and key-in all termination points.

#### SURFACE REPAIR

All depressions, divots and cracks should be profiled and free of dust and contaminants. Repair surface imperfections to reduce the ability to see the defect through the coating.

Honor all dynamic (moving) joints, static joints may be filled, use dynamic joints as initiation and termination points during application process where needed.

#### **TEMPERATURE EVALUATION**

Ambient and substrate temps should be above  $50^\circ\text{F}$  and a minimum of  $5^\circ\text{F}$  above Dew Point.

Product temps should be between 70-80°F. Relative Humidity should not exceed 80%.

Relative Humidity should not exceed 80%. See CrownTech Bulletin 7: Temperature & Relative Humidity

#### REFER TO SAFETY DATA SHEETS (SDS) FOR SAFETY PRECAUTIONS.

SAFETY PRECAUTIONS MUST BE FOLLOWED DURING STORAGE, HANDLING AND USE.

#### PERSONAL PROTECTIVE EQUIPMENT (PPE)

SHALL BE WORN AT ALL TIMES INCLUDING BUT NOT LIMITED TO LONG SLEEVE SHIRTS OR DISPOSIBLE ARM SLEEVES, SAFETY GLASSES, DISPOSIBLE NITRILE GLOVES, AND PROPERLY FITTED NIOSH RESPIRATORS

ALL SOURCES OF IGNITION SHOULD BE TURNED OFF AND ENVIRONMENT SHOULD HAVE PROPER AND ADEQUATE VENTILATION DURING APPLICATION AND CURING PROCESS

#### MIXING AREA SHOULD BE PLACED ON OR IN CLOSE PROXIMITY TO PROJECT. AREA SHOULD BE SECURELY COVERED WITH PLASTIC, CARDBOARD OR TARP. STAGE MATERIALS, TOOLS AND CLEANING SUPPLIES IN MIXING

AREA PRIOR TO APPLICATION PROCESS.

7126

#### DO NOT MIX MORE MATERIAL THAN CAN BE APPLIED IN 20 MINUTES

#### MIXING



Pre-Mix A-Component in its respective container using Jiffy mixer and drill at slow speeds for 1 minute until pigment is uniform.

IF USING MULTIPLE BATCHES, IT IS BEST TO BOX ALL A-COMPONENTS TOGETHER THEN SEPARATE BACK INTO INDIVIDUAL CONTAINERS TO ENSURE EVEN PIGMENTATION.



7

Pre-Mix B-Component in its respective container using clean Jiffy mixer and drill at slow speeds for 30 seconds or until thoroughly homogeneous.

Transfer A-component and B-component at a mix rate of 7A:1B by volume into a clean 5-gal bucket and mix for 2-3 minutes being sure to scrape sides of the bucket with a stir stick ensuring both components are thoroughly blended

# COVERAGE RATE

300 Lf / Gal @ 1/4" x 1/4"

#### SLIP RESISTANCE

Skid-Resistance – Field (in situ) Wet Dynamic Coefficient of Friction (DCOF), ANSI A326.3. See Crown Polymers Technical Bulletin: 4 Coefficient of Friction.

## CLEAN-UP

**CrownFlex Aliphatic Polyurea Joint Filler** 

Clean-up mixing station, tools, and equipment as required. Use acetone, a VOC exempt solvent, for cleaning up. Observe all legal, and health, and safety precautions when handling or storing solvents and materials, particularly in confined spaces. Make sure the working areas are well ventilated at all times during placement and curing time.

#### DISPOSAL

Dispose of empty packaging and other waste in accordance with federal, state, provinces and local regulations.

#### MAINTENANCE

Inspect the installed floor by spot cleaning and spot repairing the damaged or cracked areas. To prolong life of the flooring system, a daily maintenance program is highly recommended to ensure the floor is safe for its intended purposes. See Crown Polymers Technical Bulletin: 8 Care and Maintenance.

## **TECHNICAL SUPPORT**

For questions, contact a Crown Polymers Representative. Additional Support Documents are available from Crown Polymers, including brochures, application guidelines, videos and more. Visit Crownpolymers.com or contact Crown for additional resources

## WORKING TIME

10 Minutes @ 75°F

WARMER AMBIENT, PRODUCT AND SURFACE TEMPERATURES WILL SHORTEN POTLIFE AND WORKING TIME.

## APPLICATION PROCEDURE



Use putty knife or flat squeegee to apply mixed material to prepared joints and cracks



Allow coating to dry 1 Hr @ 75°F

Do not force dry. Once dry, shave excess material flush with razor scraper Light Traffic: 24 Hours

Heavy Traffic: 48 Hours