

PHYSICAL PROPERTIES

voc		<100 g/L
SOLIDS CONTENT		38.5%
VOLUMETRIC MIX RATIO	•••••	2A:1B
COVERAGE RATE	•••••	350 ft²/gal 4.6 Mils
APPLICATION TEMP	•••••	50°- 90°F
POTLIFE 1 Gal mass @ 75°F		45 Mins
DRY TIME @ 75°F	•••••	2-6 Hours
RECOAT WINDOW		Indefinite
FULL CURE	•••••	24 Hours
PACKAGING		1.5 Gal Kit 15 Gal Kit

MECHANICAL PROPERTIES

GLOSS INDEX 60° ASTM D523		Gloss: 90-95
		Satin: 40-70
PENCIL HARDNESS ASTM D3363	•••••	ЗН
ADHESION TO CONCRETE ASTM D7234		>300 p.s.i

CHEMICAL RESISTANCE

Refer to CrownTech Chemical Resistance Guideline Technical Bulletin No. 9 Technical Data Sheet (TDS)

PRODUCT DESCRIPTION

8105 CrownSeal Acrylic Polyurethane Primer/Sealer is a low viscosity, two-component acrylic polyurethane designed as a primer for Polyurethanes, such as 8110 CrownSeal CRU and as a concrete sealer. It is a film-forming sealer that leaves the surface with a wet look. It is a non-yellowing UV stable sealer that is available in clear gloss and clear satin. It cures to an inert, tough, concrete sealer. The recoat window, different than all other polyurethanes, is limitless, just make sure the surface is clean and free of contaminates. It is ideal for use as an irregular surface sealer, such as cementitious knockdowns, where an acrylic sealer is unacceptable. For added durability, place a second sealer coat. Apply 8105 CrownSeal Clear between 300 to 350 sq. ft. or 8105 CrownSeal Clear Satin between 400 to 450 sq. ft. (Not intended for use as a primer for epoxy coating or cementitious overlayments.) It is designed for use in Southern California and is in compliance with SCAQMD air quality standards for Industrial Use Only.

TYPICAL USES

Aircraft Hangars & Maintenance Floors
Automotive Show Room and Repair Areas Commercial Bakeries and Kitchens
 Hospital and Health Care Facility Floors Laboratories and Research Floors

 Manufacturing and Warehouse Floors School & Universities

 Pharmaceutical Floors

BENEFITS

- Complies with USDA, FDA, FSMA. See Crown Polymers Technical Bulletin: 3 Food and Beverage Compliance.
- Slip Resistance (ADA)
 See Crown Polymers
 Technical Bulletin: 4
 Coefficient of Friction.

LEED requirements. See
Crown Polymers Technical
Bulletin: 5 LEED information

Cures to an inert
finish. See Crown Polymers
Technical Bulletin: 2 VOC
Compliance

COLORS



Clear Satin

LIMITATIONS

SHELF LIFE

unopened

- Do not add additional solvents
- Satin requires a prime coat first

• Prime with 8303 if MVT is above 3 Lbs

• Do not apply below 30% Relative Humidity

STORAGE

Store in a dry environment at room temperature and out of direct sunlight.

1 Year from Date of Manufacture provided

APPLICATION EQUIPMENT

Personal Protective Equipment Jiffy Mixing Paddle Drill 18"x 1/4" Nap Shedless Roller Cover 5-7 Mil Notched Squeegee 4" Chip Brush Spike Shoes

SURFACE DIAGNOSTICS

Concrete must be structurally sound and free of all contaminants and bond breakers. Test concrete compressive strength using a Schmidt or Rebound Hammer to ensure substrate has compressive strength of 3500 psi or higher.

Perform a PH test using concrete PH test strips or meter to ensure substrate PH is between 9-12.

Perform Moisture Test using either Calcium Chloride per ASTM F1869 or In-Situ Relative Humidity Probe per ASTM F2170 to ensure substrate has Moisture Vapor Emission Rate of 3 lbs or less and Relative Humidity of 80% or less. See CrownTech Bulletin 6: Moisture Mitigation Negative Side Moisture Barrier

If Moisture Vapor Emission Rate is above 3 lbs. but below 25 lbs. and relative humidity is above 80% but below 99% then apply 8303 Moisture Barrier Primer first at 16 mils with a coverage rate of 100 Ft²/ Gal.

SURFACE PREPARATION

Use Mohs scratch test to determine concrete hardness for proper diamond bond selection.

Concrete should be mechanically profiled and prepared to produce a Concrete Surface Profile (CSP) level between #2 & #4 per ICRI Guideline no. 310.2R. See CrownTech Bulletin 1: Concrete Surface Preparation. All perimeter areas of coating termination shall be masked for protection. Saw cut and key-in all termination points.

SURFACE REPAIR

All depressions, divots and cracks should be profiled and free of dust and contaminants. Repair surface imperfections to reduce the ability to see the defect through the coating.

Honor all dynamic (moving) joints, static joints may be filled, use dynamic joints as initiation and termination points during application process where needed.

TEMPERATURE EVALUATION

Ambient and substrate temps should be above 50°F and a minimum of 5°F above Dew Point.

Product temps should be between 70-80°F.

Relative Humidity should not exceed 80%. See CrownTech Bulletin 7: Temperature & Relative Humidity

REFER TO SAFETY DATA SHEETS (SDS) FOR SAFETY PRECAUTIONS.

SAFETY PRECAUTIONS MUST BE FOLLOWED DURING STORAGE, HANDLING AND USE.

PERSONAL PROTECTIVE EQUIPMENT (PPE)

SHALL BE WORN AT ALL TIMES INCLUDING BUT NOT LIMITED TO LONG SLEEVE SHIRTS OR DISPOSIBLE ARM SLEEVES, SAFETY GLASSES, DISPOSIBLE NITRILE GLOVES, AND PROPERLY FITTED NIOSH RESPIRATORS ALL SOURCES OF IGNITION SHOULD BE TURNED OFF AND ENVIRONMENT SHOULD HAVE PROPER AND ADEQUATE VENTILATION DURING APPLICATION AND CURING PROCESS

MIXING AREA SHOULD BE PLACED ON OR IN CLOSE PROXIMITY TO PROJECT. AREA SHOULD BE SECURELY COVERED WITH PLASTIC, CARDBOARD OR TARP. STAGE MATERIALS, TOOLS AND CLEANING SUPPLIES IN MIXING AREA PRIOR TO APPLICATION PROCESS.

DO NOT MIX MORE MATERIAL THAN CAN BE APPLIED IN 20 MINUTES

MIXING PROCEDURE

Pre-Mix A-Component in its respective container using Jiffy mixer and drill at low RPMs for 30 seconds to ensure components are fully suspended.

Pre-Mix B-Component in its respective container using clean Jiffy mixer and drill at slow speeds for 30 seconds or until thoroughly homogeneous.

Transfer A-component and B-component at a mix rate of 2A:1B by volume into a clean 5-gal bucket (if adding aluminum oxide add #220 a rate of 1/2 lb./gal or #320 at a rate of up to 3 lbs./ gal) and mix for 2-3 minutes at low RPMs being sure to scrape sides of the bucket with a stir stick ensuring both components are thoroughly blended

COVERAGE RATE

350 Ft² / Gal @ 4.6 mils

WORKING TIME


15-25 Minutes @ 75°F

WARMER AMBIENT, PRODUCT AND SURFACE TEMPERATURES AS WELL AS HIGHER RELATIVE HUMIDITY WILL SHORTEN POTLIFE AND WORKING TIME.

APPLICATION PROCEDURE

Cut-in edges using a 4" chip brush. Do not allow wet edges to stand more than 10 minutes ahead of application of main body of floor.

PRODUCT SETS SLOWER IN MASS, MIXED MATERIAL SHOULD BE POURED AS NEEDED



- Maintain wet edge
- Always pour next mixed batch onto wet edgeDo not apply heavier than recommended
- coverage rates

Back roll the surface with 18" x 1/4" nap roller by walking into the wet material wearing spike shoes and roll the surface wall to wall with overlap perpendicular to your first pass • Do not overwork material

Allow coating to dry 2-6 Hrs @ 75°F Do not force dry. Light Traffic: 24 Hours Heavy Traffic: 48 Hours Equipment Traffic: 72 Hours

SLIP RESISTANCE

Skid-Resistance – Field (in situ) Wet Dynamic Coefficient of Friction (DCOF), ANSI A326.3. See Crown Polymers Technical Bulletin: 4 Coefficient of Friction.

CLEAN-UP

Clean-up mixing station, tools, and equipment as required. Use acetone, a VOC exempt solvent, for cleaning up. Observe all legal, and health, and safety precautions when handling or storing solvents and materials, particularly in confined spaces. Make sure the working areas are well ventilated at all times during placement and curing time.

DISPOSAL

Dispose of empty packaging and other waste in accordance with federal, state, provinces and local regulations.

MAINTENANCE

Inspect the installed floor by spot cleaning and spot repairing the damaged or cracked areas. To prolong life of the flooring system, a daily maintenance program is highly recommended to ensure the floor is safe for its intended purposes. See Crown Polymers Technical Bulletin: 8 Care and Maintenance.

TECHNICAL SUPPORT

For questions, contact a Crown Polymers Representative. Additional Support Documents are available from Crown Polymers, including brochures, application guidelines, videos and more. Visit Crownpolymers.com or contact Crown for additional resources

DISCLAIMER

All guidelines, recommendations, statements. and technical data contained herein are based on information and tests we believe to be reliable and correct, but accuracy and completeness of said tests are not guaranteed and are not to be construed as a warranty, either expressed or implied. It is the user's responsibility to satisfy himself, by his own information and test, to determine suitability of the product for his own intended use, application and job situation and user assumes all risk and liability resulting from his use of the product. We do not suggest or guarantee that any product limitations are the only ones which may exist. Neither Seller nor Manufacturer shall be liable to the buyer or any third person for any injury, loss or damage directly or indirectly resulting from use of, or inability to use, the products. Recommendations or statements, whether in writing or oral, other than those contained herein shall not be binding upon the Manufacturer, unless in writing and signed by an authorized corporate officer of Manufacturer. Technical and application information is provided for the purpose of establishing a general profile of the material and proper application procedures. Test performance results were obtained in a controlled environment and Manufacturer makes no claim that these tests or any other tests accurately represent all environments. Manufacturer is not responsible for typographical errors.



Scan QR code for full Disclaimer and Limited Warranty information





2